

HIRVATİSTAN LİMANLARINDA TÜRK BAYRAKLI GEMİLERDE 2022-2023-2024 YILINDA TESPİT EDİLEN EKSİKLİKLER
(Tutulma maddeleri Gri Renkli olarak verilmiştir)

DENETİM LİMANI	DENETİM TARİHİ	NO	REFERANS	EKSİKLİK
SPLIT	19.02.2022	1	SOLAS ch.IV R.7	Navtex printout bearly readable. Message from Split Radio station is missing.
		2	SOLAS ch.V R.27	BA CHART 269 last two updates missing.
		3	SOLAS ch. III R.20	ITU list IV Edition 2019 found on board. NP47 not included voyage plan to Split.
	18.03.2022	1	SOLAS ch.V R.27	ITU list IV Edition 2019 found on board.
		2	SOLAS ch. II-2 R.45	Emergency Escape doors in E/R not closing properly.
	13.02.2023	1	SOLAS ch.IV R.4	Navtex not set to receiving from Adriatic region (Letter Q)
		2	SOLAS ch. III R.32.2	Two life jackets light on navigation bridge expired on 09/2022.
		3	MLC 2006 Std A3.1	Galley ventilation hood greasy.
		4	MLC 2006 Std A4.3	Grinder/wire brush machine in E/R missing.
	29.03.2023	1	SOLAS ch. III R.20	Rescue boat engine running in period less than 3 min.
29.03.2023	1	SOLAS ch.IV R.4	Navtex device not received from Split radio. Not selected (Letter Q).	
RIJEKA	29.08.2023	1	SOLAS CH II/R.14.2	Self closing doors in galley can not be closed. Closing arm is broken and locking mechanism is not working. CO2 protecetd paint locker doors can not be cosed.
		2	SOLAS CH.V/R.27	Rijeka port (BA chart 2719), Rijeka approach (BA chart 1996) and Kvarner area (BA chart 202) are missing. Vessel was in Rijeka port two weeks ago.
		3	SOLAS CH.V/R.34	Route not plotted on nautical charts. Positions not plotted on nautical chart.
		4	ICLL AN. I/R.15	Several cleats on hold No. 1 and hold No.2 are missing or are damaged
		5	COLREG/RULE 20	Both stern anchor lights are not working
		6	SOLAS/II-1/R.26	Rescue boat emergency light not working
		7	ISM CODE- SOLAS/IX/R.3	Corrective action taken on the ISM system by the Company is required within 3 months, Deficiency(s) marked ISM is (are) objective evidence of a failure, or lack of effectiveness, of the implementation of the ISM Code.The ship will be eligible for reinspecton after 3 months from the final date of the report.
		8	SOLAS/R.19	Fire drill in galley failed.
		9	ICLL/R.23	Watertight window in oiler's cabin which is situated on main deck is leaking water
		10	MLC/STD. A4.3	Common bathroom door frame is corroded with sharp edges on door's treshold.
		11	MLC/STD A3.1	Oiler's cabin on upper deck floor found damaged with holes