

LİTVANYA LİMANLARINDA TÜRK BAYRAKLI GEMİLERDE 2022-2023-2024 YILLARINDA TESPİT EDİLEN EKSİKLİKLER
(Tutulma maddeleri Gri Renkli olarak verilmiştir)

| DENETİM LİMANI | DENETİM TARİHİ | NO | REFERANS | EKSİKLİK |
|-----------------|-------------------|----------|------------------------|--|
| KLAİPEDA | 26.03.2023 | 1 | COLREG An. I /5 | The sidelight inboard secreens painted partially White, partially glossy black paint instead of matt black paint. |
| | | 2 | SOLAS Ch.II -1 R.45 | Loud speaker on bow mooring station – cable is not secured in such way as to avoid chafing damage, also connection is made only with electrical insulating tape, and not repaired permanently. |
| | | 3 | BMW 2004 An. II | Ballast water discharge operations under code 3.3.2. does not have Rob indicated. |
| | | 4 | MLC Std A3.2 | Freezers indicate temperatures too low such as -27,-38,-42 degrees Celcius |
| | 31.10.2023 | 1 | ANNEX/ APPENDIX II | Quantity of ballast stated in the Ballant water record book and Ballast water management plan are different than International ballast water certificate. |
| | | 2 | MLC/STD. A3.2 | Rotten cabbage and potatoes have been found in provision store. Wooden pallets stored on the floor are rotten. Overall cleanliness is unsatisfactory. |
| | | 3 | SOLAS/ch.II2/r.14 | CIC deficiency: Some fire flaps got no rubber gaskets, or gaskets are painted. |