

POLONYA LİMANLARINDA TÜRK BAYRAKLI GEMİLERDE 2022-2023-2024 YILLARINDA TESPİT EDİLEN EKSİKLİKLER
(Tutulma maddeleri Gri Renkli olarak verilmiştir)

DENETİM LİMANI	DENETİM TARİHİ	NO	REFERANS	EKSİKLİK
GDANSK	24.04.2023	1	SOLAS Ch.II-2 R.45	Means of escape between bridge assembling station and lower platform PS found obstructed by unknown boxes. Marking label for assembling station not well visible on aft captain deck.
		2	MARPOL Annex VI Ch.6.2	ME and A/E's record boks found with missing. Reuired entries/ not up to date. Master instructed with immediate affect to proper entries in RB of engine parameters.
		3	MLC 2006 Std. 3.2	MEAT/fish provision room refrigerating system pipes found with many ice accretion
		4	MLC 2006 Std.4.3	Many not secured containers with chemicals found stowed in steering gear room.
		5	SOLAS Ch.II-2 1994-1998 R.17	During fire drill both rescuers enter of scene of fire without BA. Master instructed with immediate effect to carried out proper training for crew members.
		6	SOLAS 99/00 Amend Ch.IX R.3	Corrective action taken on ISM system by the company is repuired within 3 months. Deficiency marked ISM is objective evidance of a failure or lack of effectivenessof the implementation of ISM Code. The ship will be eligible for reinspection after 3 moths from final date of the report
		7	SOLAS Ch. IX R.4	SMC found expired. Flag Administration extend validity of certificate
		8	SOLAS Ch. II- R.14.1	Main fire line on deck leakage observed on flange connections.
		9	ISPS Code Part A 19	ISSC found expired from 24/04/2023. Flag Administration extend validity of certigicate till 25/04/2023
		10	SOLAS Ch.V R 12	Starboard side bridge wing gyro repater showing wrong indications not synchorized.
		11	MARPOL An. I R.15	Seven drums with chemicals stored on main deck between cargo holds.
		12	MLC 2006 R.4.3	Portside mooring/anchor winch standing platform floor plates not secured by screws before any movements.
		13	MLC 2006 R.4.3	Paint locker found stowed in mess with open lids paint and solvent buckets.
		14	MARPOL An. I 2015 Amend. R.14	Engine crew unable to present record from OWS 15 ppm bilge alarm record device which corresponding with ORB bilge water disposal to O/B entrance from 14/04/2023

SZCZECIN

24.01.2023

1	SOLAS Ch.II-1 R.26	Aux. Engine No:1 exhaust gas leakage
2	SOLAS Ch.II-1R.26	Aux. Engine No:2 exhaust gas leakage
3	SOLAS Ch.II-1R.26	Aux. Engine No:3 exhaust gas leakage
4	SOLAS Ch.II-1R.27	Aux. Engine No:1 automathic shut-off arrangements in the case of failures of lubricatingoil supply failure inoperative.
5	SOLAS CIV 2018 R10	One INMARSAT C printer- inoperative.
6	SOLAS C.IV R.7.1.3	Safety pin on one SART broken
7	SOLAS Ch.II R.29	Steering gear alarm panel located on the bridge indicates following alarm. No:2 pump overload
8	MARPOL An. IV R.29	Air blower No:1 missing manual preparing instruction for sewage treatment plant missing
9	MARPOL An. I R.7	Supplement to IOPP certificate item 2.2.2(oil filtering equioment) marked as not applicable