

LİTVANYA LİMANLARINDA TÜRK BAYRAKLI GEMİLERDE 2022-2025 YILLARI ARASINDA TESPİT EDİLEN EKSİKLİKLER
(Tutulma maddeleri Gri Renkli olarak verilmiştir)

DENETİM LİMANI	DENETİM TARİHİ	NO	REFERANS	EKSİKLİK
KLAIPEDA	26.03.2023	1	COLREG An. I /5	The sidelight inboard secreens painted partially White, partially glossy black paint instead of matt black paint.
		2	SOLAS Ch.II -1 R.45	Loud speaker on bow mooring station – cable is not secured in such way as to avoid chafing damage, also connection is made only with electrical insulating tape, and not repaired permanently.
		3	BMW 2004 An. II	Ballast water discharge operations under code 3.3.2. does not have Rob indicated.
		4	MLC Std A3.2	Freezers indicate temperatures too low such as -27,-38,-42 degrees Celcius
	31.10.2023	1	ANNEX/ APPENDIX II	Quantity of ballast stated in the Ballant water record book and Ballast water management plan are different than International ballast water certificate.
		2	MLC/STD. A3.2	Rotten cabbage and potatoes have been found in provision store. Wooden pallets stored on the floor are rotten. Overall cleanliness is unsatisfactory.
		3	SOLAS/ch.II2/r.14	CIC deficiency: Some fire flaps got no rubber gaskets, or gaskets are painted.
	24.02.2025	1	COLREG	Inboard screens for a sidelights are glossy black, not matt black as required
		2	BWM 2023	Non conventional format of Ballast water record book. Tank diagram is missing
		3	BWM 2004	Ballast water treatment system is malfunctioning. D-1 standard only can be followed
		4	MARPOL	Numerous garbage containers got wooden covers.
		5	MLC 2006	3 angle grinders equipped with cutting disc found without protection in cargo store Both aft and forward mooring winches clutch mechanism is not secured by the pin.