

Denetim Limanı	Den. Tarihi	Uzman (PSCO)	Type	Gross	Keel Date	RO		Eksiklik Maddesi	Ref.	Eksiklik Kodu
						Safety Cert.	SMS			
BAKAR	12.01.2018	Vladimir Malnar Milivoj Andracka	Chemical Tanker	4236	2007	BV	BV	Shipboard working arrangements not in form required by STCW	STCW	17
								BDN for last bunkering does not contain all relevant data	MARPOL	17
SPLIT	9.10.2018	Mare Vukić	General Cargo	1995	18.08.1989	TL	TL	Navtex messages text printout not clearly visible.	SOLAS ch. IV - Reg 7.1.4	17
								Fire hose on main deck aft and one fire hydrant on main deck fwd is leaking.	SOLAS ch. III - 2 Reg 14.2	17
								Last passage plan incomplete the distance between Split pilot and discharging port not recorded / covered.	STCW Code Part A / A-VIII / 2 / Part 2	17
	12.11.2018	Daubor Markić Mare Vukić	General Cargo	2034	21.03.1982	TL	TL	During Fire Drill some crewmembers looking through open door at fire scene.	SOLAS Chp. III Reg 19	17
								Oil leakages in steering gear room.	SOLAS Chp. II-1 Reg 29	17
								WC and sink in deck cadet's cabin sanitary facility leaking.	MLC 2006 T.3 Std. A.3.1	17
								Amounts of Bilge and sludge in ORB wrong calculated.	MARPOL Annex I Reg. 17	17
								Both Hru of liferaft expired in 10/2018	SOLAS Chp. III Reg 15	17
								Lights on LifeJackets expires in 06/2018	SOLAS Chp. III Reg 32.2	17
								BA chart 200 is not up to dated.	SOLAS Chp. V Reg 27	17
ITU List last edition 2017 found in on board.	SOLAS Chp. V Reg 27	17								
Corrective action taken on the ISM System by the company is required within three months.	ISM Code	21								
SIBENIK	27.11.2018	Perisan Krona	General Cargo	1243	6.01.1996	TL	TL	Rubber Mats (protective) in forecandle in front of starting panels missing.	MLC 2006 T.4 Std. A.4.3	17
RIJEKA	22.12.2018	Emil Marinov	General Cargo	5962	20.11.1981	BV	NK	Voyage plan does not include UKC and ship's speed.	SOLAS ch. V - Reg 34	17
								Fire plan is not showing fire doors.	SOLAS ch. II - 2 Reg 15.2	16
								Fuel samples found in area not protected by fixed fire system	SOLAS ch. II-2 Reg 2	17
	5.01.2019	Emil Marinov	General Cargo	1905-	18.08.1989	FS	TL	Unprotected gangway and unsecure access to the ship. Vessel's gangway without protective net and unfolded platform.	ICLL 1988 Reg 25	17
								Rescue boat can not hold full air pressure. Boat needs to be inflated in frequent intervals.	Solas Chp. III Reg. 20	16
							Ventilation for cargo hold No.2 can not be closed properly because threaded shaft is out of center.	SOLAS ch. II - 2 Reg 14.1	16	

								Some lifejackets not marked with Ship's name. Previous ship's name stenciled.	Solas Chp. III Reg. 20	17	
								Visitor ID not checked.	ISPS Code Part A/7	17	
	24.01.2019	Mladen Mandlc / Emil Marinov	General Cargo	2477	15.06.2004	FS	FS	Passage plan does not containing ship's speed. Positions are not plotted on navigational charts. Charts are containing several routes from past voyages.	SOLAS ch. V Reg 34	17	
	23.04.2019	Zoran Paskvan	General Cargo	3989	1.03.1990	FS/TL	TL	Fire door for entering in to the engine room closing device damaged, not closing properly	SOLAS ch. II - 2 Reg 47	17	
PLOCE		14.11.2018	Toni GRGIY	General Cargo	3136	21.05.1982	TL	TL	Emergency fire pump not properly maintained shoul be easier to start.	SOLAS	17
		10.12.2018	Toni GRGIY	General Cargo	4981	1.06.1981	BV/TL	BV	Vdr alarm is blinking.	SOLAS V R.20	10
									Lifebouy light nil lightining on stb side boat deck.	SOLAS III R. 21	10
									MLC repatriation documents not posted in messroom.	MLC 2006	10
									MLC shipowners liability documents not posted in messroom.	MLC 2006	10
		22.02.2019	N.BECKSA/ V. VASIO	General Cargo	2997-	29.06.1984	TL	TL	Fire dampers in port side e/r not as required.	Solas II-2	10
								Lifeboat reflector stripes blocked by wire and in poor condition.	LSA 96	10	
								Stb. Lifeboat engine insulation in poor condition	Solas III	17	