

Denetim Limanı	Den. Tarihi	Uzman (PSCO)	Type	Gross	Keel Date	RO		Eksiklik Maddesi	Ref.	Tutulma Maddesi
						Safety Cert.	SMS			
	30.01.2018	Dorian Raducu	General	942	1978	İDARE	TL	Compass error book missing	SOLAS	17
								Forward deck and poop deck winches area anti slippery substance missing	MLC	17
								SOPEP Oil spill kit list inventory list missing, rectified during psc	MARPOL AN 1	10
	4.03.2018	Mihai Babus Laurentiu Zanfir	General	996	1980	TL	TL	1 aft rope damaged	LOADLINE	17
	9.03.2018	Vicentiu Hincu Dorian Raducu	General	1587	1998	TL	TL	E/R one fire door class A keep it hooked in open position	SOLAS	17
								Garbage record book wrong records (port name, discharge of garbage to reception facilities missing) Master instructed to keep proper records from now on.	MARPOL AN 5	99
								Engine room shipboard working arrangements poster missing.	STCW	17
	10.05.2018	Lucian Tomita Laurentiu Zanfir	General	2102	2005	BV	BV	2nd eng. employment contract expired since April 2018.	MLC	17
	10.06.2018	Mihai Babus	Other	8323	2001	ABS	NKK	1 forward rope damaged.	MLC 2006	17
								Radio log incomplete records. The communications relating to safety traffic not recorded. Master instructed to keep proper records from now on.	SOLAS 88 C IV	99
	15.06.2018	Dorian Raducu	Bulk Carrier	25938	2000	NKK	NKK	Cargo Ship safety equipment certificate, Form E, Item 2.1 incorrect recorded. Deficiency rectified by NKK surveyor during PSC Inspection.	S98 CI R12	10
								Compass error is not determined at least once a watch. Master instructed to keep proper records from now on.	STCW P A VIII	99
	01.07.2018	Vicentiu Hincu	Container Ship	15479	2007	BV	NKK	SOPEP Annex 2 is not updated.	MARPOL A1 R 37	17
								Fire door from E/R entrance not closed properly. Self closing device not adjusted.	SOLAS CII-2	17
	22.08.2018	Lucian Tomita	General	1249	1982	İDARE	TL	Access ladder from gangway to main deck with hand rails missing	MLC 2006	17
								Records of rest forms not as required. Details like month and year, rank on board, ship's name, ship's flag etc. Records of rest for July 2018 not signed by crew.	MLC 2006	17
								Last voyage plan not berth to berth. Constanta pilot embarkation point not recorded, UKC missing.	SOLAS CV R34	17
								VHF DSC test with coastal radio station not performed and records are missing.	88 Am. C IV R17	17
								VHF DSC test carried out with Constanta Radio station. Reception of acknowledge failed.	01 Am. C IV R7.1.1	17
	04.09.2018	Mihai Babus	General	2132	2003	TL	TL	Last passage plan not cover the voyage from departure berth to arrival berth. Several required publications not recorded.	S C V R34	10
								Insufficient records of navigational activities to restore the ship's voyages. (e.g. distances sailed, position fixing, changes to voyage plan are missing) Master instructed to keep proper records from now on.	S C V R28	99
								Starboard side freebord mark partly unreadable/rusty.	LL 1988	17
								Garbage record book Part II - records missing.	M AN 5 R6	17
No MSDS for available for bunker operation carried out on 30.07.2018.								S CVI R 5-1	10	
Insufficient quantity of fresh vegetable and fruits.								MLC2006 R 3.2	17	

CONSTANTA							Certificate in copy available on board. Official letter Ref no 65856 issued by Turkish Flag Administration on 04.09.2018 confirm that the original certificate will be received on board before departure.	Bunker 2001	48	
							Cargo hold no 1, two starboard frames found bent.	ICLL R 1	17	
							ISM eksikliği, düzeltici faaliyet	ISM	21	
	24.09.2018	Mihai Babus	General	2149	1981	TL	TC	Steering gear ventilation closing device found stuck in open position.	SOLAS C II-2	10
								Maximum rate of discharge for untreated sewage missing.	MARPOL IV R11	17
								Last CSR document (no 5) partly unreadable/wasted.	SOLAS CXI R5	16
								Oil record book, incorrect bunkering quantities filled up. Master instructed to keep proper records from now on.	MARPOL AN 1 R17	99
								Last passage plan incomplete. Distance from Constanta pilot station to arrival berth not covered, required nautical publications not recorded.	SOLAS CV R34	17
								One forward rope damaged.	MLC 2006	17
								MF/HF DSC external test incomplete - acknowledgement not received from shore station.	SOLAS CIV R10	17
								ISM eksikliği, düzeltici faaliyet	ISM	21
	07.02.2019	Hincu Vicentiu	General	2991	2006	TL	TL	Accommodations ladder lower platform two stancions missing and safety net not properly fixed.	MLC	17
								Standard compass error is not determinate at least once a watch - Master instructed to keep proper records from now on.	STCW	99
	11.03.2019	Dorian Raducu	General	2445	1978	TL	TL	Compass error is not determined at least once a watch. Master instructed to keep proper records from now on.	STCW	99
								Last voyage plan wrong information (inserted sailing directions NP 48 and 49, out of sea passage area) Deficiency rectified during PSC inspection.	SOLAS C V	10
	25.03.2019	Dorian Raducu	General	1868	1998	TL	BV	Compass error is not determined at least once a watch. Master instructed to keep proper records from now on.	STCW	99
								Last voyage plan not approved by master. Deficiency rectified during PSC inspection.	SOLAS C V	10
	19.04.2019	Mihail Babus	General	12930	1989	ABS	ABS	Different value of length (Article 2(8)) stated in International tonnage certificate and in International Loadline Certificate.	ICLL 88 Protochol	16
								Starboard draught scales and freeboard mark partly unreadable.	ICLL 88 Protochol	17
								Lifeboat launching instructions, provided in the vicinity of survival crafts are in English language only. Working language on board is Turkish.	SOLAS 96	10
	23.05.2019	Mihail Babus	General	996	1978	TL	TL	One aft and one forward mooring rope worn out.	MLC 2006	17
								Insufficient records of navigational activities to restore the ship's voyages. (e.g .Ships position, weather and sea conditions.) Master instructed to keep proper records from now.	SOLAS C V	99
								Emg. towing booklet not customized according crew componce. (e.g item 3.2 - Tasks and equipment)	SOLAS II-1	17
							Garbage management plan not customized according crew componce (e.g items 5.3 and 5.4 - Collection and storing/disposal)	Marpol An 5	17	
							Radio log incomplete records. Only the regulary tests recorded. Master instructed to keep proper records from now on.	SOLAS CIV	17	
							Noon reports evidence missing - Master instructed to keep proper records from now on.	SOLAS C V	99	

								Last voyage plan incomplete. The distance between the Constanta pilot station and arrival berth not covered.	SOLAS C V	17
								Seafarers Employment Agreement (SEA) required information missing. (e.g leave pay, safarers address and contact details are missing.)	MLC 2006	17
								Garbage record book incorrect entries (the quantities are not recorded for each disposed category). Master instructed to keep proper records from now on.	Marpol AN.V	99
	28.06.2019	Hincu Vicentiu	Konteyner	15479	2006	NKK	NKK	Inmarsat C secondary means not work properly starting in last voyage from TEKIRDAG port in Turkey on 19.06.2019. Floopy driver inoperative. Substitute with one provisional flash memory but not working more than 5-6 hours.	Solas 2004 R IV	81
							Master Mr Muhittin REIS found with S.E.A expired from 07.06.2019.	MLC 2006	17	
GALATI	13.03.2018	Sarbu M / Moisei P.	General	5469	1988	TL	TL	Magnetic compass not readable, insufficient light.	SOLAS	17
								Garbage disposal placards near collecting area, Poop deck missing.	MARPOL	17
	19.03.2018	Sarbu M / Moisei P.	General	906	1992	TL	TL	Magnetic compass not readable	SOLAS	17
	27.03.2018	Sarbu M / Moisei P.	General	4998	1984	TL	TL	One door aft accommodation, Boat deck not closing properly.	ICLL	17
	03.04.2018	Sarbu M / Moisei P.	General	1572	1991	BV	TL	SOPEP Annex 2 not updated	MARPOL AN 1	17
								Funnel door, boat deck not closing properly	MARPOL	17
	09.06.2018	Sarbu M / Moisei P.	General	2184	1986	TL	TL	Shipboard Working Arrangement Table in Turkish	MLC 2006	17
								Record of rest in Turkish Language only.	STCW PART A	17
								Magnetic compass not readable (insufficient light)	SOLAS 88-90 CV	17
	01.08.2018	Moisei Paul	General	2914	1995	BV	TL	International AFS certificate issued instead of cert.of compliance for AFS.	AFS 2001 ANNEX 4	16
								Magnetic Compass not readable	SOLAS C V R 12	17
								Navigation bridge one window wiperwith blade damaged.	SOLAS C V R 22	17
	05.09.2018	Ftadeev Gh.	General	1511	1994	TL	TL	DMLC compliance Part II, in copy on board.	MLC 2006	16
								BA chart 2213 missing.	S V 5 R 27	17 /Detention
								Ship overloaded	ICLL 88 Prt.	17 /Detention
							NP 86 Vol N old edition	S CV R 27	17	
							Not evidence that the standart compass error is determined at least once a watch. Master instructed to keep properly records from now on.	STCW Code Part A	99	
							Fire drill failed, not properly mustered, poor communication, BA equipment and fire wire lines not used, fire squad incomplete.	Solas 13 C III R 19	17 /Detention	
							SMS audit by Administration befor departure.	ISM	19/Detention	
25.09.2018	Moisei Paul	General	1854	1976	TL	TL	Lifebuoys not as required - one lifebuoy with light inoperative	S60 CIII R21	17	
							Two whether tight doors outside accommodation, with rubber gasket damaged/worn out.	ICLL 88 Prt.	17	
10.10.2018	Moisei Paul	General	2435	1981	TL	TL	Radio log, only tests recorded. Muster instructed to fill up properly from now on.	SOLAS 88 C IV	99	
							One emergency light, boat deck, inoperative.	SOLAS 74 CII-1	17/10	
							Garbage disposal placards near collecting area, Poop deck missing.	MARPOL AN 5	17.Eki	
	15.07.2018	Moisei P.	General	2120	2005	RINA	TL	Four life jackets on bridge not marked.	SOLAS CIII	17
								Garbage disposal placards near collecting area, poop deck, missing	MARPOL AN V	17/10
								Two emergency lights on boat deck inoperative.	SOLAS II-1 R 44	17
	24.12.2018	Ftadeev Gh.	General	4998	1984	TL	TL	SOPEP plans and drawings in Italian Language.	M AN I R37	16

BRAILA	27.12.2018	Ftadeev Gh.	General	4338	1984	TL	TL	ME fuel pipes insulation partly damaged.	MLC 2006	17
	07.03.2019	Moisei P.	General	2132	2003	TL	TL	Radio Log not as required. Only tests recorded, Master instructed to fill up properly from now on.	SOLAS 88 CIV R17	99
								Shipboard working arrangements table missing information regarding minimum hours of rest or max hours of work.	MLC 2006	17
								Magnetic compass not readable (light inoperative)	SOLAS CV R19.2.1	17
21.03.2019	Moisei P.	General	4988	1983	TL	TL	Shipboard working arrangement table not posted on bridge and Engine Control Room.	STCW CODE	17	
MIDIA	12.10.2018	Dorian Raducu	General	2997		NKK	NKK	Compass error is not determined at least once a watch. Master instructed to keep proper records from now on.	STCW Part A	99
								GMDSS Log books GOC's holder info for ship's master missing.	SOLAS C IV R 17	17
								Last voyage plan lack of information (Admiralty List of Lights, Sailing directions, Radio signals and more)	SOLAS CV R34	17
								Fire safety operational booklet incomplete/missing (section 7 not updated)	SOLAS C II-2 R 16	17
MANGALIA	28.01.2019	Mihai Babus	General	2565	1984	TL	TL	Radio log book incomplete. Only the regulary tests recorded. Master instructed to keep proper records from now on.	SOLAS C IV	99
								Compass correction log book not updated. Master instructed to determinate the corrections as per requirements from now on.	STCW PART A 4.1	99
	11.02.2019	Tiberiu Calborenau	General	2561	1984	TL	TL	Garbage Record Book, garbage, other than cargo residues recorded on Part II.	MARPOL ANNEX 5	17
								Quantity of F/O bunkered not recorded in tonnes. D/O leakage tank mentioned as sludge tank in ORB, is not recorded in supplement of IOPP certificate as oil residues (sludge tank) - item 3.1	MARPOL ANNEX 1 R 17	17
							Record of equipment (form E) for cargo ship safet equipment item 2, 2.1, 5., 5.1 to be amended as appropriate.	SOLAS 1988 Amend	17	
TULCEA	09.05.2019	Ftadeev Gh.	General	2102	2005	BV	BV	Egzost gas pipe Emergency Diesel Generator on main deck corroded.	SOLAS II-I	16
								Bridge stbd clear-view window inoperative.	SOLAS C V	17
								Fixed CO2 system, CO2 fire system pipes on main deck port side partly corroded.	SOLAS II-2	16
								Freeboard marks partly unreadable.	LL	17
								Galley ceramic floor partly damaged.	MLC	16