

Denetim Limanı	Den. Tarihi	Uzman (PSCO)	Type	Gross	Keel Date	RO		Eksiklik Maddesi	Ref.	Eksiklik Kodu
						Safety Cert.	SMS			
SZCZECIN	16.03.2018	Andrzej HABURA Gregorz KEDZIERSKI Dariusz OBLICKI	Chemical Tanker	3478	13.02.2008	BV	BV	Electronic nautical publications - activation key expired on 28.02.2018 on one computer.	Solas Ch.V Reg.27	17/10
								IOPP certificate - original missing (only copy available on board)	MARPOL An.I-Reg. 7	16
								IAPP certificate - original missing (only copy available on board)	MARPOL An.VI-Reg. 7	16
								ISPP certificate - original missing (only copy available on board)	MARPOL An.IV-Reg. 5	16
								CLC Bunker certificate - original missing (only copy available on board)	Bunker 2001	16
								CLC Oil Pollution Damage certificate - original missing (only copy available on board)	CLC 1992 Protocol	16
								CSS Equipment certificate - original missing (only copy available on board)	SOLAS 1988 /Ch.I (Hssc)/ Reg. 12	16
								CSS Construction certificate - original missing (only copy available on board)	SOLAS 1988 /Ch.I (Hssc)/ Reg. 12	16
								CSS Radio certificate - original missing (only copy available on board)	SOLAS 1988 /Ch.I (Hssc)/ Reg. 12	16
								IcoF Dangerous chemicals in Bulk - original missing (only copy available on board)	IBC Code -1/1.5	16
								Safety pin on one SART broken.	Solas Ch.IV Reg.7.1.3	17
								VDR control panel indicates ALARM	Solas Ch.V Reg.20	10
								Corrective action taken on the ISM system by the company is required with in 3 months.	ISM Code	21
	5.06.2019	Andrzej HABURA Sylwester WLODARZ	Chemical Tanker	3478	13.02.2008	NKK	NKK	Name of ship not entered	AFS 2001-An.4	16
								Certificate of compliance of VDR-missing	SOLAS Ch.V Reg.18	17
								Toilet bowl on the brdige-flushing inoperative	MLC 2006 Title 3 Reg.3.1	17
								Sewage treatment plant draining pump inoperative	MARPOL An.IV Reg. 9	17
								Incinerator quick closing valve's gear worn out and causing problems with keep v/v in open position	SOLAS Ch.II-2 Reg.4.2	17
								Auxiliary Engine no:3 starting motor faulty	SOLAS Ch.II-1 Reg.26	17
Swinoujscie	13.04.2018	Andrzej HABURA Gregorz KEDZIERSKI Dariusz OBLICKI	Bulk Carrier	27581	24.01.2001	NKK	NKK	Fire Safety	Solas Ch.II-2 Reg.17	17/10
								Life saving appliances	LSA Code Reg.6	17/10