

FRANSA LİMANLARINDA TÜRK BAYRAKLI GEMİLERDE 2022-2023-2024 YILINDA TESPİT EDİLEN EKSİKLİKLER
(Tutulma maddeleri Gri Renkli olarak verilmiştir)

DENETİM LİMANI	DENETİM TARİHİ	NO	REFERANS	EKSİKLİK
MARSİLYA	23.10.2022	1	MLC 2006 R. 3.2	Meat and fish room found with too much hoarfrost on compressorRotten tomatoes found in vegetables room.
		2	SOLAS C II-2 R14	One powder extinguisher in E/R 1rst floor PS found empty.
	20.11.2023	1	SOLAS CH.II-2	Electrical breaker for boiler 1 circulating pump n°1 inoperative (thermal oil)
		2	MLC TITLE 3	Temperature log of cold room not filled for month of november
SAINT MALO	09.06.2023	1	SOLAS C II-2 R14	Emergency generator room is not fitted with fire detectionto be checked with Flag Adminstration.
		2	SOLAS C II-2 R14	Fire dampers of emergency generator room not closing properly (inlet not fully closing and outlet not working)