

MALTA LİMANLARINDA TÜRK BAYRAKLI GEMİLERDE 2022-2025 YILLARI ARASINDA TESPİT EDİLEN EKSİKLİKLER
(Tutulma maddeleri Gri Renkli olarak verilmiştir)

DENETİM LİMANI	DENETİM TARİHİ	NO	REFERANS	EKSİKLİK
VALLETTA	29.04.2022	1	ISPS / Part A7/7.2	Gangway security not carried out.
		2	SOLAS Ch.III R.37.4.5	Substitutes for key personel and officer responsible for the maintenance of LSA/FFA not indicated muster list.
		3	MLC Title 4 Reg.4.3	Eye wash missing near chemicals (Personal equipment missing)
		4	SOLAS Ch.II-2 Reg.3.1.1.3	Emergency light from emergency exit in engine room inoperative.
		5	SOLAS Ch.II-2 R.4.1.1	One EEBD is found empty. Replaced with spare. Empty one to give ashore for filling
		6	MLC Title 1 Reg1.2.	Registered officer about medical has expired medical certificate on 24/03/2022