

Denetim Limanı	Den. Tarihi	Uzman (PSCO)	Type	Gross	Keel Date	RO		Eksiklik Maddesi	Ref.	Eksiklik Kodu
						Safety Cert.	SMS			
MARSİLYA	9.01.2018	Richard TURA Alexandre FEKKAR	General Cargo	2927	29.12.2008	İDARE	TL	At the time of inspection Chart 155 Missing on board.	SOLAS Ch.V Reg.27	17
								At the time of inspection vessel neither provided air compressor or suitable number of spare cylinders for BA during drills.	SOLAS Ch.II-2 Reg.15-2	16
								At the time of inspection CO2 system found with safety pins engaged on all remote controlled bottles.	SOLAS Ch.II-2 Reg.14-2	10
								At the time of inspection ballast water record book not mentioning any BW exchange operations and/or reasons why exchange has not been performed.	BWM 2004 B/Reg. B-4	16
	09.09.2018	Serge HEYRAUD MASSON Fabien	General Cargo	6852	15.10.2008	İDARE	BV	1st Eng. Could not test properly OWS	Marpol An. I Reg.14	17
22.03.2019	Charles DESMOULIS Alexandre FEKKAR	Chemical Tanker	3547	15.02.2002	ABS	ABS	At the time of inspection, Forward isolation valve of main fire line found not watertight.	SOLAS Ch.II-1 1991-1992 Am.Reg.4	10	
							At the time of inspection, first attempt of black out squence leads to failure of automatic connection to esb. After investigation and repair, 2nd test satisfactory.	SOLAS Ch.II-1 1996-1998 Am.Reg.43	10	
SETE	24.10.2018	Cedric FRADIN Philippe MARTINEZ Claire FOURNEAUX	Chemical Tanker	2222	18.12.2007	ABS	ABS	For all crew members on board August 2018 wages were only paid on October 15, 2018 and September 2018 wages have not been paid yet.	MLC 2006 Title 2 Reg.2.2	17-Groun for Detention
								Ballast water record book not mentioning ballast water exchange during last voyages	BWM 2004 B/Reg. B-4	17
LORIENT	28.11.2018	Jean Marc CAVEAR Rebecca PASQUERRAU Benoit VINCENT	General Cargo	4937	10.06.1998	KRS	TL	At the time of inspection, many lights of inoperative; -rescue boat launching on starboard side,-boat launching on port side,-all outside lighting (normal and emergency) from accommodations to forecastle	SOLAS Ch.II-1 1991-1992 Am.Reg.43	10
								At the time of inspection, subtitles for key persons are not mentioned on the muster list. Due date:12.12.2018	SOLAS Ch.III 1996-1998 Am.Reg.37	99
LE HAVRE	30.07.2019	Remi LAMEITRE Thomas FOSSIER	Chemical Tanker	4165	4.11.2008	RINA	RINA	Light in ballast pump room is operative (except for emergency lighting)	MLC 2006 Title 4 Reg.4.3	17