

Denetim Limanı	Den. Tarihi	Uzman (PSCO)	Type	Gross	Keel Date	RO		Eksiklik Maddesi	Ref.	Tutulma Maddesi
						Safety Cert.	SMS			
KOPER	04.07.2018	Sandro Gasparini	General	4910	2004	TL	TL	Oil record book, bunker quantities not entered in tonnes.	MARPOL AN 1	17
								Steering gear pumps No 1 & 2 indicators on bridge and engine control room indicates alarm - phase failure .	SOLAS CII-1 R 29	17
								Epirb antenna is broken.	SOLAS CIV R 15	17
	27.09.2018	Goran Mrdenovic	General	1960	1990	TL	TL	Head lines (2 pcs) worn out.	MLC 2006 4.3	16
								Insufficient food, lack of fruit and vegetables, meat, fish	MLC 2006 3.2	17
								Continuous synopsis record - missing forms 2 and 3 for the amendments and indices for CSR documents No 1, 2,3,6 and 7.	SOLAS CXI-1 R5.4.1	16
								Incomplete checking of the identity of all persons seeking to board the ship at the access point, incomplete visitors log. Access control of the vessel is not ensured.	ISPS Code Part A	17
	29.10.2018	Goran Mrdenovic	Chemical	4450	1992	NKK	NKK	Echo sounder out of order	SOLAS C V	48
								Plimsol mark and draught marks not readable	LOAD LINE R 5	17
								Portable fire extinguishers, EEBD, BA expired 18.10.2018	SOLAS C II-2	17
	09.05.2019	Sandro Gasparini	Chemical	1803	2007	TL	BV	Bow draught marks not readable	SOLAS C II-1	17
								Oil record book part 1 - entries for bunkering and weekly collection of oil residues not filled in properly.	Marpol Annex 1	17
Remote quick closing valve for Diesel Oil storage tank not ready for use.								SOLAS C II-2	10	